



Alameda Clash Report

Jun 12, 2020



**ASU Alameda
Warehouse**



ID [1](#)

 None

[Open](#)

Title
staging area (194) Verify Light Layout and elevations(clashing with joists)

Assignee
Mouli Nouri


Reporter
Mouli Nouri

Created
Jun/03/2020

Deadline
Not set

Project
ASU Alameda Warehouse

[Open in Revizto](#)



ID [2](#)

 None

[Open](#)

Title
men's restroom (111M1) Confirm Duct Penetration Locations to avoid Beam

Assignee
Mouli Nouri


Reporter
Mouli Nouri

Created
Jun/03/2020

Deadline
Not set

Project
ASU Alameda Warehouse

[Open in Revizto](#)




ID [3](#) None Open

Title
Access Control (113U1) Exhaust duct going through a beam, coordination needed

Assignee
Mouldi Nouri
Reporter
Mouldi Nouri
Created
Jun/03/2020 Deadline
Not set
Project
ASU Alameda Warehouse

[Open in Revizto](#)




ID [4](#) None Open

Title
Lockers room(111V1) Return round duct clashing with domestic cold water pipe, positioned too close to the light fixture

Assignee
Mouldi Nouri
Reporter
Mouldi Nouri
Created
Jun/04/2020 Deadline
Not set
Project
ASU Alameda Warehouse

[Open in Revizto](#)




ID [5](#) None Open

Title
Women's restroom(111W1) Return and Exhaust duct clashing with sewer pipe and domestic cold water pipe respectively

Assignee
Mouldi Nouri
Reporter
Mouldi Nouri
Created
Jun/04/2020 Deadline
Not set
Project
ASU Alameda Warehouse

[Open in Revizto](#)




ID [6](#) None Open


Title
Receiving room (190) Hose bib located at rolling door (190c)/ pipe clashing with door

Assignee
Mouldi Nouri
Reporter
Mouldi Nouri
Created
Jun/04/2020 Deadline
Not set
Project
ASU Alameda Warehouse

[Open in Revizto](#)



ID [7](#)

 None

[Open](#)

Title
Auction area(182) Light Fixture clashing with a return duct

Assignee
Mouldi Nouri


Reporter
Mouldi Nouri

Created
Jun/08/2020

Deadline
Not set

Project
ASU Alameda Warehouse

[Open in Revizto](#)



ID [8](#)

 None

[Open](#)

Title
Unisex restroom (180T) Light fixture clashing with a supply duct

Assignee
Mouldi Nouri


Reporter
Mouldi Nouri

Created
Jun/08/2020


Deadline
Not set

Project
ASU Alameda Warehouse

[Open in Revizto](#)



ID [9](#)

 None

[Open](#)

Title
Auction space(182) Multiple light fixtures clashing with return and exhaust ducts.

Assignee
Mouldi Nouri


Reporter
Mouldi Nouri

Created
Jun/08/2020


Deadline
Not set

Project
ASU Alameda Warehouse

[Open in Revizto](#)



ID [10](#)

 None

[Open](#)

Title
Receiving area(190) near door 190D Electrical fixture clashing with a vertical return duct.

Assignee
Mouldi Nouri


Reporter
Mouldi Nouri

Created
Jun/08/2020

Deadline
Not set

Project
ASU Alameda Warehouse

[Open in Revizto](#)




ID [13](#) None Open

Title
Maintenance/staging area (194) 8" Drainage pipe clashing with electrical fixture GFCI Duplex Receptacle.

Assignee
Mouldi Nouri
Reporter
Mouldi Nouri
Created
Jun/08/2020
Deadline
Not set
Project
ASU Alameda Warehouse

[Open in Revizto](#)




ID [14](#) None Open

Title
Tech area(191A) Electrical fixture clashing with 2" Sewer pipe.

Assignee
Mouldi Nouri
Reporter
Mouldi Nouri
Created
Jun/08/2020
Deadline
Not set
Project
ASU Alameda Warehouse

[Open in Revizto](#)




ID [15](#) None Open

Title
lockers area(111V1) Behind the two drinking fountains Electrical Fixture clashing with a 2" sewer pipe.

Assignee
Mouldi Nouri
Reporter
Mouldi Nouri
Created
Jun/08/2020
Deadline
Not set
Project
ASU Alameda Warehouse

[Open in Revizto](#)




ID [18](#) None Open

Title
Loading dock-Receiving area (190) Miss alignment between underground drain storm location and drainage pipe coming from the roof.

Assignee
Mouldi Nouri
Reporter
Mouldi Nouri
Created
Jun/12/2020
Deadline
Not set
Project
ASU Alameda Warehouse

[Open in Revizto](#)



ID [19](#)

None

[Open](#)

Title
Men's restroom (111M1) Multiple Sanitary pipes going through the footing.

Assignee
Mouldi Nouri


Reporter
Mouldi Nouri

Created
Jun/12/2020

Deadline
Not set

Project
ASU Alameda Warehouse

[Open in Revizto](#)



ID [20](#)

None

[Open](#)

Title
Managed area (195) Sewer main pipe is miss aligned with sanitary pipe coming from the restrooms to the north of the building by 8' 6".

Assignee
Mouldi Nouri

Reporter
Mouldi Nouri

Created
Jun/12/2020

Deadline
Not set

Project
ASU Alameda Warehouse

[Open in Revizto](#)



ID [21](#)

None

[Open](#)

Title
East side, Self Managed area (104) Fire line pipe is not reaching the sprinklers main pipe, miss aligned by 13'6".

Assignee
Mouldi Nouri


Reporter
Mouldi Nouri

Created
Jun/12/2020

Deadline
Not set

Project
ASU Alameda Warehouse

[Open in Revizto](#)



ID [22](#)

None

[Open](#)

Title
Self Managed area(104) Domestic water pipe is miss aligned by 11'4".

Assignee
Mouldi Nouri


Reporter
Mouldi Nouri

Created
Jun/12/2020

Deadline
Not set

Project
ASU Alameda Warehouse

[Open in Revizto](#)



ID [23](#)

None

[Open](#)

Title
Staging area(194) Verify duct work placement against rolling door railings

Assignee
Mouldi Nouri


Reporter
Mouldi Nouri

Created
Jun/12/2020

Deadline
Not set

Project
ASU Alameda Warehouse

[Open in Revizto](#)



ID [24](#)

None

[Open](#)

Title
Moving area(108) verify duct work placement against rolling door railings

Assignee
Mouldi Nouri

Reporter
Mouldi Nouri

Created
Jun/12/2020

Deadline
Not set

Project
ASU Alameda Warehouse

[Open in Revizto](#)